DALY, CROWLEY, MOFFORD & DURKEE, LLP

354A Turnpike Street - Suite 301A CANTON, MASSACHUSETTS 02021-2714

TELEPHONE: 781-401-9988

FACSIMILE: 781-401-9966

CHRISTOPHER S. DALY JUDITH C. CROWLEY DONALD F. MOFFORD PAUL D. DURKEE

KERMIT ROBINSON ANTHONY T. MOOSEY

OF COUNSEL MARIANNE M. DOWNING

November 1, 2006

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

RE:

U.S. Patent of Roy P. McMahon

Patent No.:

7,060,905

Issued on:

June 13, 2006

Entitled:

ELECTRIC CABLE HAVING AN ORGANIZED SIGNAL PLACEMENT AND ITS

PREPARATION

U.S. Appl. No.: 09/990,723

Our Ref. No.:

RTN-267PUS

Dear Sirs:

Enclosed are two completed copies of Form PTO/SB/44. It is requested that a Certificate of Correction be issued to correct the listed mistakes in the above-identified patent.

Authorization to charge the payment of \$100.00 to cover the cost of the Certificate of Correction in accordance with 37 C.F.R.§1.20(a) is hereby given and please charge Deposit Account 50-0845.

Very truly yours,

Donald F. Mofford

Donald & MML

DFM/pam **Enclosures** 39784

PTO/SB/44 (02-01)

Approved for use through 01/31/2004, OMB 0651-0033 U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO

: 7,060,905

DATED

: June 13, 2006

INVENTOR(S): Roy P. McMahon

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4, lines 15-16 delete "because it the electrical" and replace with -because the electrical--.

Column 8, line 58-59, delete "structure 52,54)" and replace with --structures 52,54)--.

MAILING	ADD	RESS	OF	SENDER:

DALY, CROWLEY, MOFFORD & DURKEE, LLP 354A Turnpike Street, Suite 301A Canton, MA 02021-2714

7,060,905 PATENT NO. _

No. of additional copies

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comment on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Commissioner for Patents, P. O. Box 1450, Alexandria, VA 22313-1450

PTO/SB/44 (02-01) Approved for use through 01/31/2004. OMB 0651-0033

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO

7,060,905

DATED

June 13, 2006

INVENTOR(S):

Roy P. McMahon

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4, lines 15-16 delete "because it the electrical" and replace with -because the electrical--.

Column 8, line 58-59, delete "structure 52,54)" and replace with --structures 52,54)--.

MAILING ADDRESS OF SENDER:

PATENT NO. ___

7,060,905 No. of additional copies

DALY, CROWLEY, MOFFORD & DURKEE, LLP 354A Turnpike Street, Suite 301A

Canton, MA 02021-2714

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comment on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Commissioner for Patents, P. O. Box 1450, Alexandria, VA 22313-1450